

This report is not a NYCDEP published, documented report. It is a summary of a phone conversation between DCC, Inc. and Chief of Operations at the Gilboa Dam. Report prepared by S. Bartholomew, DCC, Inc. President.

Gilboa Dam Rehab Update
9/8/10
John Vickers-Chief of Operations
Via phone call

1. Gates: began in May full force
 - a. Install fall protection for workers
 - b. Placed anchors in notch
 - c. Poured concrete in anchor channels
 - d. Excavated for air lines for bladders
 - e. Piping is in place-everything stainless steel
 - f. These are to be encased in concrete
 - g. Separate airlines for each bladder
 - h. 11 gates-20' long with 2 bladders for each gate
 - i. low pressure of 140 lbs/sq inch
 - j. one extra gate and 2 extra bladders on site for replacement if something happens.

2. Control unit
 - a. Foundation has been poured for temporary control building on western abutment
 - b. Upper gate chamber rehabilitation is proceeding
 - c. Permanent controls will be installed in upper gate chamber/western side parapit
 - d. Old low level valves will be filled in with concrete-no threat to safety

3. operation of gates from grahamsville?
 - a. Manned 24/7
 - b. Not 24/7 from Gilboa-not a resident engineer on 24 hours
 - c. Operators are trained for multiple emergencies
 - i. Earthquakes
 - ii. Floods
 - iii. Alarm redundancy
 - iv. Position elevations at dam, etc.
 - d. Immediate call to Gilboa police station to engage emergency
 - e. Can correct some things from there
 - f. Camera installed to monitor gates only
 - g. Lots of early warning and instrumentation installed in gates
 - h. Stand by generator
 - i. Air lines still function with out electricity for a period of time. Low pressure

4. siphons:
 - a. in place until winter of 2011/2012
 - b. contractor controls when they are to be removed
 - c. it should be a 2 year window of no siphons or LLO
 - d. Intake chamber can handle siphon output providing ashokan is not full
 - e. Not able to meet snow pack management plan not a problem because it was an agreement not a requirement
 - f. Suggested pumps and they feel that the size would have to be too large, no place for them on dam spillway surface

5. Union college sensors-
 - a. Sensor buried on left side of 990 V bridge due to moving of stilling pool which had to be move to install piers for bridge
 - b. Sensor seems to be buried

6. Bridge is coming along

7. Stilling pool was moved

8. Low Level Outlet:
 - a. Did make trip to utah
 - b. Redesigned llo valve bldg. Hood 80" X 210'
 - c. Energy dissipation will take place inside bldg.
 - d. Water will slide down slide to creek below creek bank where there were concerns about erosion.
 - e. Provision in design of "Y" upstream of hood to put in generator for hydro
 - f. Working on math model that will take in account condition of snow pack and info provided by NWS to make better decisions concerning water draw down for snow pack mp
 - g. It is a 3 year study.
 - h. Basing information on kensico reservoir study. Called an operation support tool

9. Western Access road almost completed

